

PROJECT PROPOSED BY RURUMA WARD RESIDENTS THROUGH A FORUM CONDUCTED ON
6th SEPTEMBER 2021

1. BOFU PRIMARY SCHOOL
 - a) Administration Block
 - b) Two Classrooms
 - c) Renovation of 8 Classrooms
 - d) Water Harvesting equipment
 - e) Wiring of all classrooms
 - f) Fencing of School Compound.

2. KAWALA PRIMARY SCHOOL
 - a) Renovation of Five Classrooms
 - b) Administration Block
 - c) Water harvesting equipment
 - d) Fencing of School Compound

3. Mikomani Primary School
 - a) Renovation of Eight Classrooms
 - b) Twenty door number pit latrines
 - c) Water harvesting equipment
 - d) Borehole
 - e) Ten number classrooms
 - f) Administration Block
 - g) Library and store
 - h) Lightning arresters
 - i) 200 pcs Desk –Priority number one

4. MWANJAMA PRIMARY SCHOOL
 - a) Administration Block
 - b) Twelve number door pit latrine
 - c) School fence

5. MAKANZANI PRIMARY SCHOOL
 - a) Administration Block
 - b) Renovation of Eight Classrooms
 - c) Six Door number pit latrines

6. MASAANI PRIMARY SCHOOL
 - a) Six door number pit latrine
 - b) Administration Block
 - c) Renovation of Two Classrooms
 - d) Furniture for teachers.

7. JIMBA SECONDARY SCHOOL
 - a) Twin Science Lab
 - b) Administration Block
 - c) Three Classroom
 - d) School Bus
 - e) Fencing of School Compound

- f) Modern Kitchen
- g) Six number Door pit latrine
- h) Staff quarters
- i) Dormitories
- j) Landscaping
- k) White boards

8. KAWALA GIRLS SECONDARY SCHOOL

- a) Twin laboratory
- b) Administration Block
- c) 200 pcs lockers/chairs
- d) School fence
- e) Water tank of 10000ltrs

9. MLEJI PRIMARY SCHOOL

- a) 100 pcs of Hard Wood Desks
- b) Eight doors pit latrines
- c) Administration Block
- d) Renovation of Three Classrooms
- e) School fence

10. JIMBA PRIMARY SCHOOL

- a) Eight Door number pit latrine
- b) School Fence
- c) Renovation of Three Classrooms
- d) School library
- e) Administration Block

11. KASIDI PRIMARY SCHOOL

- a) Three Classrooms
- b) Administration Block
- c) Twelve door pit latrines.

12. KASIDI SECONDARY SCHOOL

- a) Twin Science Laboratory
- b) Administration Block
- c) Fencing of the School Compound
- d) Four Classrooms

13. BOFU SECONDARY SCHOOL

- a) Four Classrooms
- b) School bus
- c) Ten Doors pit latrines
- d) 150 stools for the Laboratory
- e) School Library

14. MAWE MABOMU PRIMARY SCHOOL


- a) Four classroom
- b) Administration block
- c) 200 pcs of Hard wood desk

- d) Water harvesting equipment
- e) Six door number pit latrine

15. SECURITY

- a) Ruruma Police station
- b) Four door number toilets in all the assistance and chiefs office
- c) Fencing of all assistant chiefs offices.


Photos of ward representatives



Signed by


Mariam Ali Mohammed
NG-CDFC Chairlady

Report Signed By


Hezron Koech
Deputy County Commissioner

DEPUTY COUNTY COMMISSIONER
KABAI SUB-COUNTY