


MINISTRY OF EDUCATION

STATE DEPARTMENT FOR EARLY LEARNING AND BASI EDUCATION

ISO 9001:2008 Certified

Email address: deo.gilgil@yahoo.com

Ref. No. MOE/GIL/GEN/vol 3/48



SUB-COUNTY EDUCATION OFFICE

P.O. BOX 501

GILGIL

19TH January, 2021

The Fund Manager

NG-CDF

Gilgil


Constituency.


RE: REQUEST FOR AN OFFICIAL VEHICLE

I am kindly requesting your office to provide us with an official vehicle to enable us visit schools during our routine work.

This will enable us perform our work well. It will also assist in transportation of National Examination to schools to avoid inconvenience caused as a result of sharing because we normally borrow from other departments.

Thank you in advance.



ERIC OBIRI
SCDE
GILGIL



MINISTRY : DEVOLUTION AND PLANNING, NC-CDF BOARD STATION-GILGIL CONSTITUENCY

N.B. Columns 1 to 6 to be completed by the Department prior to the Assembly of the Board

1 ITEM NO	2 ARTICLE	3 QUANTITY	4 DATE OF PURCHASE	5 ORIGINAL VALUE	6 STATE WHETHER UNSERVICEABLE OR SURPLUS	7 BOARD'S REPORT ON CONDITION ECONOMICALLY TO REPAIR	8 RECOMMENDATION OF BOARD FOR DISPOSAL	9 ESTIMATED LOCAL SALEABLE VALUE IF SALE IS RECOMMENDED NOT RECOMMENDED	10 REMARKS
1	LAND ROVER DEFENDER 110 (GKB 430H)	1	8 TH APRIL 2015	6,124,120.00	SERVICEABLE		DONATION		
2									
3									
4									
5									
6									
7									
8									
9									
10									



JOHN K KAMAU CHAIRMAN - Regional Mechanical Engineer
 JOHN MICHUKI MEMBER - (Chairman CIDFC)
 MARTIN THUO MEMBER - District Accountant
 PETER CHEGE MEMBER - CIDFC Secretary
 WILSON MUTEGI SECRETARY - (Sub-County Procurement Officer)
 DATE: 29/03/2021

CPS (SP)

DECISION OF:-
 ACCOUNTING OFFICER DATE:
 TREASURER DATE:
 For (about Secretary National Treasury)



MINISTRY OF TRANSPORT AND INFRASTRUCTURE

REGIONAL MECHANICAL ENGINEER
NAKURU REGION
P.O BOX 660-20100
NAKURU

OUR REF: M/NKU/7/VOL.IIX/241

TO: NG - CDF
GILGIL

Your Ref/MR No: D1693793
Your Ref Date: 25/3/2021
Job No: 659

VEHICLE MECHANICAL INSPECTION REPORT

VEHICLE REG. No: GK B430H MAKE/MODEL: Land Rover TYPE: Caravan

USER DEPT: NG-CDF Gilgil MINISTRY: of Devolution & Planning

ENGINE NO: Not Accessed CHASSIS NO: SALLDHMR7FA462904

INDICATED MILEAGE: 139,820 Kms

ENGINE: Serviceable

COOLING SYSTEM: Replace U/S expansion tank cap

CLUTCH: Serviceable

GEAR BOX: Check and repair transfer gearbox leakages

TRANSMISSION: Replace worn front propeller shaft universal joints

REAR AXLE: Replace missing LHS back plate & U/S RHS

FRONT AXLE: Replace worn diff oil seal and tractor joint seal (LHS)

STEERING SYSTEM: Replace worn drop arm ball joint, tie rod ends and steering damper

SUSPENSION: Replace worn rear stabilizer bushes and link, front and rear shock absorbers

BRAKES: Replace worn rear brake disc-2 No.

ELECTRICAL: Check and repair U/S headlight, brake light and parking light

CHASSIS: No visible defects Noted.

BODY, CAB ETC: Minor body scratches. Requires spray painting. Replace worn exhaust mouting, door strikers and rubbers and floor mats.

TYRES: Front 2 No 90% worn, rear 100% worn Spare 100% worn.

DURATION OFF THE ROAD: On Road

ESTIMATED COST OF REPAIRS: Kshs.186,450/=

REMARKS: The vehicle is in good shape. Its economical to repair at the estimated cost.

INSPECTED BY: Rose Orangi. *[Signature]*

1. Authority is granted to repair this vehicle/equipment in an authorized private garage in accordance with the current laid down procurement procedures.
2. The cost of repairs should be as per the Inspection report.
3. You are advised to inform this Department where you have taken your vehicle for repairs to ascertain quality of parts and works (service) during repairs.
4. You are advised to ensure the work is inspected by this Department after completion.

JOHN K. KAMAU
REGIONAL MECHANICAL ENGINEER
NAKURU REGION

[Signature]